



THW 3

Weldment Profiles and Structural Members



THW 3: Main Tasks

(Detailed instructions on the following slides)

1. Create a 2D Truss CAD model with a weldment profile to be used in LAB 6.
2. Create a custom weldment profile and member to be used in LAB 7.
3. Save and back up files.
4. Copy and Paste screen shots from both parts into a MS Word Document, convert to PDF, and submit to Blackboard.



Part 1: 2D Truss Structure for LAB 6




Figure 1: A Simple 2D Truss Structure (dimensions in inches)




Figure 2: Weldment profile cross-section (dimensions in inches)

- This system has three truss elements with the geometry shown.
- The three truss elements have a hollow rectangular cross-sectional area of 2.089 in^2 and wall thickness 0.25 in (shown on the right above).
- Use 1060 Aluminum material
- The distance and coordinate units are inches.



Set units and sketch 3 lines in SW

The image shows the SolidWorks software interface. The main window displays a sketch of a truss structure on the Front Plane. The sketch consists of three lines forming a right-angled triangle. The vertical leg is dimensioned as 36.00, and the horizontal leg is dimensioned as 48.00. The origin is located at the bottom-left corner of the sketch. The status bar at the bottom indicates 'Fully Defined' and 'Editing Sketch1'. The left-hand side of the interface shows the Feature Tree with the following items: LK Truss_TIC9 (Default<<Default>), Sensors, Annotations, Material <not specified>, Front Plane, Top Plane, Right Plane, Origin, and (-) Sketch1. The bottom status bar also shows 'SolidWorks Premium 2011 x64 Editic 34.953in 0.503in 0in'.

Save as
YI Truss LAB6.sldprt
to c:\scratch\YI.
YI = your initials





View Weldment Toolbar

View >> Toolbars >>
Weldments

OR


Right-click on Command
Manager Tab >> check
Weldments






Create Structural Members

Choose Structural Member





Assign the weldment profile to the sketch entities



Structural Member

Message
Select sketch segments for defining path. You can rotate the profile by a specified angle.

Choose!

Selections

Standard:
ansi inch

Type:
rectangular tube

Size:
3 x 2 x 0.25

Groups:
Group1
More information on how to configure Groups on the next slide.

New Group

Settings

Path segments:
Line4@Sketch1
Line1@Sketch1
Line3@Sketch1

Apply corner treatment

RG1 0.000in

RG2 0.000in

Mirror Profile

No corner treatment →



How to Configure Groups

Select the sketch lines in groups. Cannot use construction (center) lines.


A group is a collection of related segments in a structural member. Configure a group to affect all its segments without affecting other segments or groups in the structural member.

Types of groups:

1. Contiguous - A continuous contour of segments joined end-to-end. The end point of the group can optionally connect to its beginning point.


2. Parallel - A discontinuous collection of parallel segments. Segments in the group cannot touch each other.

Joining more than 2 segments at a point is not allowed.






Locate Profile in CAD Model






Check profile (h & b) orientation/rotation





CAD model with 3 structural members




3 structural members grouped together because they have the same section.



Open a Profile to View Dimensions

1. File>Open
2. Choose .sldfp as the file type.
3. Browse to folder.





View Dimensions

The image shows the SolidWorks software interface. The main window displays a 3D model of a part with dimensions. The dimensions are: 3.00 (height), 2.00 (width), and .25 (inner width). A dimension of .50 is also shown, likely representing the radius of the rounded corners. A context menu is open over the 'Annotation' folder in the left-hand tree, showing options such as 'Display Annotations', 'Show Feature Dimensions', and 'Show Reference Dimensions'. The status bar at the bottom indicates 'Display all feature dimensions of this model.' and 'Editing Part'.

3 x 2 x 0.25 (Default <<Default>>)

- Sensors
- Annotation
- Reference
- Dimension
- Material <
- Plane1
- Plane2
- Plane3
- Origin
- Sketch1

Details...

- Display Annotations
- Show Feature Dimensions
- Show Reference Dimensions
- Show DimXpert Annotations
- Insert Annotation View
- Automatically Place into Annotation Views
- Enable Annotation View Visibility
- Go To...
- Hide/Show Tree Items...
- Collapse Items
- Customize Menu

3.00

.25

.50

2.00

*Front

Model Motion Study 1



Display all feature dimensions of this model.

Editing Part Custom ?



Section Properties

Select the Sketch, then Tools > Section Properties






Save, Back-up and Prepare to Submit

Save your part as:

- YI Truss LAB6.sldprt to c:\scratch\YI. YI = your initials
- Back up this file to USB drive as well as to the network drive. You will use this model in LAB6.
- Using Alt-Prt Scrn copy and paste picture of the entire SW window showing the model in trimetric view into an MSWord Document.
- Save the MS Word file to c:\scratch\YI. You will add to it in the following steps.





Part 2: Weldment Profile

Detailed steps are in the following slides...

1. Build a custom weldment profile and create a structural member
 - a. Create a solid 1 x 3 custom weldment profile where $h = 3$ in and $b = 1$ in.
 - b. Make sure the sketch is centered at the SW origin.
2. Make sure you click on the sketch and it is highlighted before saving.
3. Save it as 1 x 3.sldlfp in:
c:\scratch\YI\CAE Standard\Rectangular Type
4. Set the file location in SolidWorks > **Tools** > **Options** > **File Locations** > **Weldment Profiles** to:
c:\scratch\YI
5. Create a structural member to be used in Lab 7.





Create a sketch of the custom profile

Use IPS units.

The pierce point defines the location of the profile, relative to the sketch segment used to create the structural member.

The default pierce point is the sketch origin, thus center a custom profile sketch at the origin, and on the Front Plane.


One way to center the sketch at the origin is to draw a diagonal centerline from corner to corner. Then, add a relation so that the midpoint of the diagonal line is on the origin (Add relation>select origin and line>click midpoint).





Location Settings for Custom Profiles

Read the next slide before proceeding...



To populate all fields in the PropertyManager SW will look for the following file structure:

C:\scratch\YourInitials *This is the location on the local PC drive where you have writing privileges.*

Now add a folder to contain all Standards. Yours will be called "CAE Standard". The path becomes:


C:\scratch\YourInitials\CAE Standard

Now add a folder to contain all Types; Ours will be called "Rectangular Type". The path becomes:

C:\scratch\YourInitials\CAE Standard\Rectangular Type




Save the Sketch as a Library Feature Part



Before saving, **select the sketch** in the SW Feature Manager Design Tree.

The sketch icon should change to:



Save the file as a **Lib Feat Part (1x3.sldlfp)** file type in:

C:\scratch\YourInitials\CAE Standard\Rectangular Type


If the icon did not change after you saved, right-click the sketch and select **Add to Library**.

Save again.





Set the file path in SW Options

- SW>Tools>Options> System Options>File Locations.
- Select Weldment Profiles in Show folders.
- Do not delete the default directory path.
- Click Add and browse to the **c:\scratch\YI** folder
- Click OK.
- Move the new path up to the top of the list of folders.
- Leave the default directory path as is, and click OK.
- Save and close. Files from both the default path and the your new path will appear as selections in the PropertyManager when you build a new structural member.





CAD model for LAB 7



- Open a new part. Use the 1 x 3 weldment profile to create a CAD model with 4 structural members using the above dimensions.
- Rotate the profile 90° so that the h dimension is parallel to Y-axis as shown on the next slide...
- Don't do an FEA.



Rotate the profile 90° so that the h dimension is parallel to Y-axis

The image shows the SolidWorks software interface. On the left is the Feature Tree, and on the right is the PropertyManager for a Structural Member. The PropertyManager has several sections:

- Message:** Select sketch segments for defining path. You can rotate the profile by a specified angle.
- Selections:** Standard: CAE Standard, Type: Rectangular Type, Size: 1x3, Groups: Group1.
- Settings:** Path segments: Line1@Sketch2, Line2@Sketch2, Line3@Sketch2, Line4@Sketch2. Dimensions: 0.00in (G1), 0.00in (G2). Mirror profile. Alignment: Align horizontal axis, Align vertical axis. A red box highlights the rotation angle dropdown set to 90.00deg.

Below the PropertyManager, a 3D sketch of a horizontal profile is shown with a blue arrow pointing upwards, indicating the rotation direction. The bottom status bar shows "Front" view and "Motion Study 1" tab.



Save, Back-up and Submit

- Save your part as YI Beam LAB 7.sldprt to c:\scratch\YI.
- Back up this file to USB drive as well as to the network drive. You will use this model in Class.
- Using Alt-Prt Screen copy and paste picture of your SW window showing the RHS of the beam in trimetric view into the MSWord Document started in the first half of this tutorial.
- Add the usual header information. Create a PDF and submit it electronically on blackboard. Name the file Lastname Firstname THW3.pdf

