



# Getting Started with Mastercam Lathe

**May 2015**

***Mastercam* X<sup>9</sup>**

## **Mastercam® X9 Lathe: Getting Started**

Date: May 2015

Copyright © 2015 CNC Software, Inc.— All rights reserved.

Software: Mastercam X9

### **TERMS OF USE**

Use of this document is subject to the Mastercam End User License Agreement. A copy of the Mastercam End User License Agreement is included with the Mastercam product package of which this document is part. The Mastercam End User License Agreement can also be found at:

<http://www.mastercam.com/companyinfo/legal/LicenseAgreement.aspx>

### **Be sure you have the latest information!**

Information might have been changed or added since this document was published. The latest version of this document is installed with Mastercam or can be obtained from your local Reseller. A ReadMe file (ReadMe.pdf)—installed with each release—includes the latest information about Mastercam features and enhancements.

# Contents

<b>Introduction .....</b>	<b>1</b>
▶ Tutorial Goals.....	2
General Tutorial Requirements.....	2
<b>1. General Setup.....</b>	<b>5</b>
▶ Lesson Goals .....	5
▶ Getting Ready to Work.....	5
▶ Exercise 1: Loading a Machine Definition .....	8
▶ Exercise 2: Setting the Construction and Tool Planes .....	9
▶ Exercise 3: Translating the Part .....	11
▶ Exercise 4: Rotating the Part.....	12
▶ Exercise 5: Creating 2D CAD Geometry .....	15
▶ Exercise 6: Setting Up the Stock in the Main Spindle .....	17
▶ Exercise 7: Defining the Chuck Jaws .....	20
<b>2. Facing, Roughing, and Finishing the Outer Diameter .....</b>	<b>23</b>
▶ Lesson Goals .....	23
▶ Exercise 1: Facing the Part .....	23
▶ Exercise 2: Roughing the Outer Diameter.....	26
▶ Exercise 3: Finishing with a Quick Finish Toolpath.....	33
▶ Exercise 4: Backplotting the Toolpaths .....	36
<b>3. Adding Grooves and Threads.....</b>	<b>41</b>
▶ Lesson Goals .....	41
▶ Exercise 1: Grooving on the Outer Diameter: Multiple Chains .....	41
▶ Exercise 2: Grooving on the Outer Diameter: Rough Pass Only.....	47
▶ Exercise 3: Finishing with Plunge Cuts .....	48


- ▶ Exercise 4: Adding a Thread Toolpath ..... 54
- ▶ Exercise 5: Verifying the Toolpaths ..... 59
- 4. C-Axis Drilling Operations..... 63**
  - ▶ Lesson Goals ..... 63
  - ▶ Exercise 1: Making Drill Geometry ..... 63
  - ▶ Exercise 2: Adding a New Toolpath Group ..... 67
  - ▶ Exercise 3: Creating a C-Axis Drill Operation ..... 68
  - ▶ Exercise 4: Copying the Drilling Operation..... 74
  - ▶ Exercise 5: Modifying the Drilling Parameters ..... 75
- 5. Cutoff and Stock Flip..... 79**
  - ▶ Lesson Goals ..... 79
  - ▶ Exercise 1: Cutting Off the Part ..... 79
  - ▶ Exercise 2: Programming a Stock Flip ..... 83
- 6. Machining the Inner Diameter ..... 89**
  - ▶ Lesson Goals ..... 89
  - ▶ Exercise 1: Creating New Tools in the Lathe Tool Manager ..... 89
  - ▶ Exercise 2: Facing the Back of the Part..... 98
  - ▶ Exercise 3: Drilling the First Inner Diameter ..... 99
  - ▶ Exercise 4: Drilling the Second Inner Diameter..... 101
  - ▶ Exercise 5: Roughing and Finishing the Third Inner Diameter..... 104
  - ▶ Exercise 6: Adding an ID Thread ..... 109
  - ▶ Exercise 7: Refining Your Verification Results ..... 112
- 7. Post Output..... 119**
  - ▶ Lesson Goals ..... 119
  - ▶ Exercise 1: Renumbering Tools ..... 119
  - ▶ Exercise 2: Posting..... 121
- Conclusion..... 122**
  - ▶ Mastercam Resources ..... 122
  - ▶ Mastercam Documentation..... 123



Contact Us .....	124
------------------	-----




# Introduction



Mastercam Lathe delivers comprehensive turning software with powerful toolpaths and techniques. In this tutorial, you create general turning, milling (c-axis), and miscellaneous operations to program the interior core of a hose nozzle in Mastercam X9. The part requires basic lathe operations such as facing, roughing, and finishing as well as grooving and threading toolpaths.

Starting with Lesson 2, a blueprint at the beginning of each lesson provides the necessary dimensions you need to create the toolpaths. Within the parts folder that is delivered with this tutorial, you will find the original SOLIDWORKS™ part used in the tutorial.



- Nozzle - 2.SLDPRT

For your reference, the folder also provides a sample of the part after each lesson:

- Hose Nozzle - Inner Core - L1.MCX-9
- Hose Nozzle - Inner Core - L2.MCX-9
- Hose Nozzle - Inner Core - L3.MCX-9
- Hose Nozzle - Inner Core - L4.MCX-9
- Hose Nozzle - Inner Core - L5.MCX-9
- Hose Nozzle - Inner Core - L6.MCX-9
- Hose Nozzle - Inner Core - L7.MCX-9

Place these files (extracted from MCAM Lathe Getting Started-X9.zip) anywhere that is convenient on your system, but be sure to also keep unmodified copies.

Mastercam is a comprehensive CAD/CAM software program, with solutions for a wide array of machining applications. While this tutorial requires only a basic familiarity with Mastercam, its intention is to provide you with an introduction to the Lathe product. Use the resources listed at the end of this tutorial to explore and learn more about other features and functions in Lathe and in Mastercam.

## Tutorial Goals

- Set up the job by creating a stock model and fixtures.
- Move the solid model to its machine orientation and create any necessary 2D geometry.
- Create and edit tools as required by the part operations and dimensions.



---

**NOTE:** The tool numbers called out in this tutorial are the defaults listed in the default library: `Lathe_mm.Tooldb`. Your tools may have different tool numbers.

---

- Program operations to work on a part's inner and outer diameter.
- Use Mastercam's verification tools and posting to check your work.



---

**IMPORTANT:** Screen colors in the tutorial pictures were modified to enhance image quality; they may not match your Mastercam settings or the tutorial results. These color differences do not affect the lesson or the exercise results.

---

## General Tutorial Requirements

All Mastercam tutorials have the following general requirements:

- You must be comfortable using the Windows® operating system.
- The tutorials cannot be used with Mastercam Demo/Home Learning Edition (HLE). The Demo/HLE file format (`EMCX-9`) is different from Mastercam (`MCX-9`), and basic Mastercam functions, such as file conversions and posting, are unavailable.
- Each lesson in the tutorial builds on the mastery of preceding lesson's skills. We recommend that you complete them in order.
- Additional files may accompany a tutorial. Unless the tutorial provides specific instructions on where to place these files, store them in a folder that can be accessed from the Mastercam workstation, either with the tutorial or in any location that you prefer.
- You will need an internet connection to view videos that are referenced in the tutorials. All videos can be found on our YouTube channel:  
[www.youtube.com/user/MastercamTechDocs](http://www.youtube.com/user/MastercamTechDocs).


- All Mastercam tutorials require you to configure Mastercam to work in a default metric or English configuration. The tutorial provides instructions for loading the appropriate configuration file.



# LESSON 1

## General Setup

Before generating toolpaths for the part, you must prepare Mastercam and the part file. This preparation includes such tasks as selecting a machine definition and defining the stock.



### *Lesson Goals*

- Open and orient the part.
- Select a machine.
- Create 2D CAD part geometry.
- Define stock boundaries.
- Add chuck jaws.

### *Getting Ready to Work*


This tutorial includes the files you need to complete the exercises. You can find these files in the tutorial's Parts folder. Place these files on your system wherever convenient, but be sure to keep an unmodified set. In preparation for this tutorial, set up Mastercam as described here.

## ► Select configuration file


- 1 Start Mastercam using your preferred method:
  - Double-click Mastercam's desktop icon.
  - Or
  - Launch Mastercam from the Windows Start menu.
- 2 Select the default metric configuration file:



- a Select **Settings, Configuration** from Mastercam's menu.



- b Choose ...\\mcamxm.config <Metric> from the **Current** drop-down list.




- c Click **OK**.

## ► Enable Backplot in Mastercam Simulator


This tutorial takes advantage of features in the Backplot mode available in Mastercam Simulator. Mastercam X9 allows you to open either this version of Backplot or an earlier version (Classic Backplot) when you access it via the Backplot button in the Toolpaths Manager. Use the following procedure to ensure that Mastercam defaults to the more recent application.



- 1 From your Windows Start menu, select **All Programs, Mastercam X9, Utilities, Advanced Configuration**.



- 2 Select **Backplot**.
- 3 If necessary, choose the option to disable Classic Backplot from the drop-down menu.
- 4 Select **OK**.




## Exercise 1: Loading a Machine Definition

Your part file needs at least one machine group before you can create toolpaths on the part. Mastercam automatically creates a machine group for each machine you select from the machine selection menu item. To see how machine selection works, complete the following exercise.

- 1 Open the part file, `Nozzle-2.SLDPRT`, which was provided with this tutorial.
- 2 Save the part as `Hose Nozzle - Inner Core.mcx-9`.

Saving the part under a new name helps prevent your accidentally modifying the original.

- 3 From the Machine Type menu, choose **Lathe**.



Mastercam displays the available machine definitions.

Normally, you would select the machine on which you plan to cut the part. This tutorial uses Mastercam’s default Lathe machine so you can close the menu without making a choice.




**TIP:** To customize the Machine Selection lists, choose **Machine Type, Mill, Manage List** or **Machine Type, Lathe, Manage List**. For more information on the dialog box that displays, click the dialog box’s Help button.

## ► Rename the Machine Group

Machine groups store complete jobs for a specific machine. For example, if some toolpaths will be cut on a lathe, and other toolpaths on a mill, you can simply create a second machine group. Each machine group can store its own job setup information and tools, and use a different set of toolpath defaults. The toolpaths from each group will post to separate NC files.

Mastercam lets you create as many machine groups as you need to organize your work.


- 1 Right-click the machine group, and select **Groups, Rename** from the pop-up menu.



Mastercam highlights the current group name.

- 2 Type a new machine group name.

The machine group name can be anything you want, but it's best to choose a name that describes the machine and its operations.



- 3 Select **File, Save** to save the file.

## Exercise 2: Setting the Construction and Tool Planes


Traditional lathe turning applications use a very different coordinate system from milling applications. Instead of a 3D/XYZ space, a lathe coordinate system for typical turning applications is 2D, with the tool axis perpendicular to the spindle (Z axis) instead of parallel to it. In other words,

- The D (diameter) axis in Lathe is equal to the Y axis in Mill.
- The Z (length) axis in Lathe is equal to the X axis in Mill.

Mastercam includes special lathe construction planes that let you work in radius or diameter coordinates. For conventional 2D turning applications, use the Planes menu on the status bar to select the desired coordinate system.

## 10 MASTERCAM X9/ General Setup

- 1** Press **[F9]** to display axes.




The blue WCS axes appear on top of the red world axes.


- 2** Click the **Planes** menu on Mastercam's Status bar.



- 3** Select **Lathe diameter, +D +Z (WCS)**.




The Status bar indicator updates to reflect the new settings.



### Exercise 3: Translating the Part


Before you can machine the part, you need to move the geometry to its machine orientation.


- 1 Select **XForm, Translate 3D**.
- 2 Select the part and press **[Enter]**.



- 3 Make the following changes in the Translate 3D dialog box:
  - a Select the **Move** option.
  - b Choose **Top** from the Source View drop-down list.
  - c Choose **Right Side** from the Destination View drop-down list.
  - d Click **OK**.

Mastercam moves the part's geometry from the Top plane to the Right plane.





- 4 Click the **Clear Colors** button to remove the result colors from the translated geometry.
- 5 Save the file.




*Exercise 4: Rotating the Part*


In this exercise, you use Mastercam’s dynamic gnomon to rotate the part geometry and improve the view.

- 1 Right-click, and select **Isometric (WCS)** from the menu.


The graphics view changes to Isometric.



- 2 From the Xform menu, choose **Dynamic Xform**.



- 3 Select the part, and press **[Enter]**.  
4 Move the gnomon to the origin.



**TIP:** The interactive gnomon allows you to move, rotate, and align the selected geometry or the gnomon relative to the geometry. Toggle the button next to the gnomon to select either of these options.


By default, the geometry manipulation button is active when the gnomon is placed.



- 5 Confirm that the **Move** button is selected on the ribbon bar.




- 6** Select the center segment of the curved control to perform a rotation around the X axis.




- 7** Rotate the gnomon 90 degrees, or enter **90** into the on-screen input box.

Mastercam rotates the part.



- 8** Click **OK** to finalize the rotation.
- 9** Click the **Clear Colors** button to remove the result colors from the geometry.






## Exercise 5: Creating 2D CAD Geometry

Hose Nozzle - Inner Core.mcx-9 is an imported solid with no wireframe geometry. To create Lathe toolpaths in Mastercam, you need two-dimensional geometry. This exercise teaches you how to create a two-dimensional profile from a solid part.

### ► Create a level for the new profile geometry


Use levels to organize part geometry. By organizing your files into levels, you can more easily control which areas of the drawing are visible at any time and what is selectable. In this section, you create a level specifically for the 2D profile geometry that you will create in the next section.

- 1 Click **Level** in the status bar to open the Level Manager.



- 2 Create a new main level by typing **2** and **Turn Profile** in the Number and Name fields.

The new level displays in the table with zero entities. It is the new main level.




- 3 Leave the Level Manager open.



**TIP:** The Level Manager is a modeless dialog box. This means that you can leave the Level Manager on the screen as you work in Mastercam's main window. You can even move Level Manager to another monitor in a multi-monitor system.


The current level displays in the status bar.




## ► Create the profile

- 1 From the Create menu, select **Turn Profile**.
- 2 Select the part as prompted and press **[Enter]**.


The Turn Profile dialog box opens.



- 3 Use the **Spin** computation method.
  - The Spin method creates a profile by spinning the geometry about an axis.
  - The Slice method produces a profile by creating a cross-section through the geometry on the XY plane.
- 4 Reduce the Tesselation tolerance to **0.01**.
- 5 If necessary, choose the **Upper profile** option.
- 6 Click **OK**.



7 Return to the Level Manager, and hide **Level 1** to view the profile.



**NOTE:** The illustration above shows the part from the MASTERCAM TOP view.


8 Save the file.

### Exercise 6: Setting Up the Stock in the Main Spindle

This exercise teaches you how to create the stock for the part, set the parameters for the stock to create stock margins and grip length, and place the stock in the correct Z position.


Creating the stock before creating the chuck jaws makes it easier to locate the stock relative to your part. Then, when you create the jaws, you can choose to automatically position them relative to the stock.

1 In the Toolpaths Manager, expand the **Properties** group and click **Stock setup** to open the Stock Setup tab of the Machine Group Properties dialog box.



2 In the Stock section, select **Left Spindle** and click **Properties**.

The Machine Component Manager - Stock dialog box opens.



- 3 In the Name field, type in **Lathe Tutorial Stock** to name the stock setup for the main spindle.

Name:

Geometry:

- 4 Choose **Cylinder** from the Geometry drop-down selections.

Cylinder lets you create 3D bar stock by entering or selecting its dimensions. This is suitable for most turning operations.


Geometry:

Geometry:

Chord tolerance:

- 5 Click the **Make from 2 points** button.

- 6 In the graphics window, select the origin and the top of the part's back face.



Mastercam calculates the distance between the points and enters the values of the part's outer diameter (OD) and length directly into the fields in the Machine Component Manager - Stock dialog box.

OD:

ID:

Length:

- 7 Add an additional **30** mm to the Length field.

Length:

The additional stock (about 30 percent) provides enough material for the main spindle clamp to hold the stock in place during machining.



**TIP:** Fields that take number values have a built-in calculator that let you enter simple formulas directly into the field.

Length:

- 8 Confirm that the Position Along Axis is set to **0.0**, and the Axis field has **-Z** for the stock direction.

These two values determine the location and orientation of the cylinder. The center of the part's face lies on the origin, and the part is positioned along -Z.

Position Along Axis


Z:

Axis:

- 9 Select the **Use Margins** option to activate the stock margin fields.

- 10 Enter **4.2** mm in the OD margin field and **1.0** mm in the Right Margin field.

This extra material protects against collisions. Mastercam will add the margin to the stock boundary when calculating Tool Clearance warnings.




- 11 Click the **Position/Orientation On Machine** tab, and make sure the option, **Stock is drawn in position on the machine** is selected.


Geometry ☒ Position/Orientation On Machine

☒ Stock is drawn in position on the machine

- 12 Return to the Geometry tab and click the **Preview Lathe Boundaries** button to view your results.




- 13 Press **[Enter]** to return to the Machine Component Manager - Stock dialog box.
- 14 Click **OK** to accept your lathe stock setup settings.
- The left spindle stock is defined.



### Exercise 7: Defining the Chuck Jaws

In this exercise you will define the position and grip length for the chuck jaws. You can only use the method described below after the stock has been set up.

- 1 In the Chuck Jaws section, select **Left Spindle** and click **Properties**.



## 2 In the Position section:

- Select **From stock**.
- Enter **25 mm** in the Grip length field.

Mastercam uses these settings to calculate the chuck jaw's position in space using the defined stock, and to determine how much stock is being held by the chuck jaw.

Position

☒ From stock  
☐ Grip on maximum diameter


Grip length: 25.0

User Defined Position

Diameter: 127.0

Z: -147.0 From Machine

Select... ☒ Z only



Your chuck jaws settings in the Machine Component Manager - Chuck Jaws dialog box should match the following graphic.


Name: Chuck Jaws (Left Spindle)

Geometry

Chord tolerance: 0.025 Color: 109

Translucency  
Solid Transparent

Profile  
☒ Parameters Chain...

Clamping method  : Reference point on geometry

OD #1 OD #2 OD #3 OD #4

Make from 2 points...

Jaw width: 37.0  
Width step: 6.0  
Thickness: 15.0

Jaw height: 50.0  
Height step: 12.5

Position

☒ From stock  
☐ Grip on maximum diameter

Grip length: 25.0


User Defined Position

Diameter: 38.2

Z: -94.0 From Machine

Select... ☒ Z only

Preview Lathe Boundaries...






**NOTE:** If any of the other values you have differ from the values shown above, make changes to your values to match the graphic.

- 3 Click **OK** to accept these settings.


The Stock Setup tab displays with left spindle's chuck jaw defined.



- 4 Select the **Shade boundaries** option to more easily see the stock boundaries and chuck jaws you have created.

- 5 Click **OK** to close the Machine Group Properties dialog box.

- 6 Save the file.




You have prepared your part. Now you can create toolpaths.



## LESSON 2

# Facing, Roughing, and Finishing the Outer Diameter

Once you have set up your job, you can begin creating toolpaths. Several toolpaths are normally involved in machining a lathe part. In this lesson you create the toolpaths necessary to shape the outer diameter (OD) of the part. Then, you backplot the operations you created to check your work.



### *Lesson Goals*


- Apply basic lathe toolpaths to the outer diameter of the part.
- Select tools and enter cutting values for each toolpath.
- Use Quick Finish to quickly create a finish toolpath based on the rough operation you created.
- Use Backplot and its functions to check your work.

### *Exercise 1: Facing the Part*

Face toolpaths prepare the face of the part for further machining. Once the face of the part is clean, you can use it to set tools or determine tool offsets.


You do not need to chain geometry to create a face toolpath. Mastercam can create the toolpath entirely from parameters you enter in the Lathe Face Properties dialog box.

- 1** Choose **Face** from the Toolpaths menu.



- 2** Click **OK** to accept the NC Name.

The Lathe Face Properties dialog box opens.




## ► Select the tool

- 1** From the Toolpath parameters tab, select the default OD roughing tool: **T0101 R0.8 OD ROUGH RIGHT - 80 DEG.**



**TIP:** Mastercam uses different colors to represent the orientation of lathe tool inserts.

- The tool has a red insert when the insert faces away from you.
- The tool has a yellow insert when the insert faces towards you.



2 Keep all other parameters on this page at their default values.

## ▶ Enter the cutting values

1 Click the **Face parameters** tab.

The **Use stock** option is selected with the Z coordinate of the stock (1.0 mm) entered in the **Finish Z** text box.



**NOTE:** The **Use stock** option is available only if you have defined the stock boundary in Stock Setup. (See page 17.)

Toolpath parameters | **Face parameters**

Select Points...  
☒ Use stock  
☐ Finish Z...  
 1.0

Entry amount: 2.0  
☐ Rough stepover: 2.0  
☒ Finish stepover: 0.25  
 Overcut amount: 0.0  
 Retract amount: 2.0 ☒ Rapid retract  
 Stock to leave: 0.0  
☐ Cut away from center line

Tool Compensation  
 Compensation type: Computer  
 Compensation direction: Left  
 Roll cutter around corners: All  
 Maximum number of finish passes: 1

Corner...  
 Lead In/Out...  
 Filter...

2 Enter 0 in the text box, or click **Finish Z** and select the origin from the graphics window.

The finished face of the part is at the origin.

☒ Use stock

Finish Z...

0

- 3 Keep all other parameters on this page at their default values.
- 4 Click **OK** to create the toolpath.



---

**NOTE:** If you use the stock model for the start and end positions of each pass and the stock changes, the start and end positions of each pass are automatically updated when you regenerate the toolpath.

---

## *Exercise 2: Roughing the Outer Diameter*

Use rough toolpaths to quickly remove large amounts of stock in preparation for a finish pass. Roughing passes are typically straight cuts parallel to the Z-axis.

Mastercam includes several types of roughing toolpaths:

- standard rough toolpaths, which let you access all of Mastercam's roughing options
- quick rough toolpaths, which let you quickly create simple rough toolpaths with fewer options
- canned rough toolpaths, which use your machine tool's canned cycles to create the most efficient code (however, these do not offer as many options as the standard rough toolpaths)
- canned pattern repeat toolpaths, which create roughing passes in the shape of the part contour, rather than cutting parallel to the Z-axis
- dynamic rough toolpaths, which remain engaged in the material more effectively, and use more of the surface of your insert, extending the tool life and increasing the cutting speed
- contour rough toolpaths, which are useful for parts where the initial stock shape is similar to the final part shape, such as using a casting for stock

In this exercise, you create a standard rough toolpath.



---

**VIDEO:** Click the icon to see the difference between a dynamic rough toolpath and a standard rough toolpath.


---

## ► Chain the geometry

- 1 Right-click in the Toolpaths Manager. Select **Lathe toolpaths, Rough**.


The Chaining dialog box displays, and you are prompted to select an entry point.

Mastercam Lathe defaults to partial chaining.



**TIP:** Access an extensive list of commands from the Toolpaths Manager's right-click menu.

- 2 Click the geometry at the first entity (a) and then, at the last entity (b) to create a partial chain.



- 3 Click **OK** in the Chaining dialog box to accept the chain.



The Lathe Rough Properties dialog box opens.

► **Enter the toolpath parameters**

Like many other toolpaths in Mastercam, you create the rough toolpath by entering tool and cutting values.

**Select the tool**

Use the Toolpath parameters tab to select a tool, set feeds and speeds, and modify other general toolpath parameters. This tab is similar for most Lathe toolpaths.




**NOTE:** The tool numbers called out in this tutorial are the defaults listed in the default library: `Lathe_mm.Tooldb`. Your tools may have different tool numbers.

- 1 From the Toolpath parameters tab, select the default OD roughing tool: **T0101 R0.8 OD ROUGH RIGHT - 80 DEG.**

This is the same tool you used to face the part (page 24).



**TIP:** A green check next to the tool indicates that it is used in another operation.



- 2 Type **OD - Rough** in the Comment field.

Comments help identify the operation in the Toolpaths Manager. They can be output to the NC file when you post.

☐ Force tool change

Comment  
OD - Rough

Misc values ☒ Stock Update



**NOTE:** Use of comments are optional. In this tutorial, not all operations will have comments.

- 3 Keep all other parameters on this page at their default values.

Enter the cutting values

- 1 Click the **Rough parameters** tab.

Toolpath parameters Rough parameters

☒ Overlap...

Depth cuts:  
☐ Auto  
☒ Equal steps  
☐ Incremental

Depth of cut: 2.0

☐ Increments of: 0.1

Min cut depth: 0.01

Stock to leave in X: 0.2

Stock to leave in Z: 0.2

Variable depth: 0.0 % of depth

Entry amount: 2.5

Exit amount: 0.0

Cutting Method: One way

Rough Direction/Angle  
  
Angle... 0.0


Tool Compensation  
Compensation type: Computer  
☒ Optimize cutter comp in control  
Compensation direction: Right  
Roll cutter around corners: All

☐ Semi Finish...  
☒ Lead In/Out...  
☐ Plunge Parameters...  
☐ Filter...  
☐ Tool Inspection...


Stock Recognition  
Disable stock recognition  
Adjust Stock...

☒ ☐ ☐

- 2 Increase the Stock to leave in X to **0.5**.




- 3 Select **Use stock for outer boundary** from the Stock Recognition drop-down.



**TIP:** Stock recognition lets you adjust how the stock is removed by the roughing operation. When you select the **Use stock for outer boundary** option, the operation uses more passes to remove material and avoids excessive cut depths.

- 4 Click the **Lead In/Out** button.




The Lead In/Out dialog box opens.

The parameters in this dialog box control how the tool approaches and/or retracts from the part for each pass in the toolpath. This eliminates the need to create extra geometry for this purpose.

- a Click the **Lead out** tab.

The Lead in and Lead out tabs have identical options for creating entry and exit moves. This allows you to set different values for each move and to combine different types of moves.






**b** Select the **Extend/shorten end of contour** option.

**c** Extend the distance of the chained contour by **5.0** mm.

Extending the distance of the part's contour will stabilize it during the cutoff operation.

**d** Enter **90** in the Angle field.

This is the angle the tool follows as it retracts from the part.






**TIP:** Set the angle of the entry or exit vector by dragging the pointer to the desired orientation. Mastercam automatically enters the new angle in the Angle field.



- e Click **OK** to return to the Lathe Rough Properties dialog box.
- 5 Keep all other parameters on this page at their default values.
- 6 Click **OK** to create the toolpath.



- 7 Save the part.


### Exercise 3: Finishing with a Quick Finish Toolpath

Use finish toolpaths to have the tool follow the contour of chained geometry. Typically, a finish toolpath follows a roughing toolpath.

In addition to standard finish toolpaths, which let you access all of Mastercam's finish toolpath capabilities, Mastercam also includes quick finish toolpaths, which let you quickly create a finish toolpath based on a previous operation (but with fewer options), and canned finish toolpaths, which finish canned rough or pattern repeat toolpaths.

Quick finish toolpaths are useful for placing finish passes on an uncomplicated part where you don't need all of Mastercam's more advanced finishing options. You can chain geometry for this toolpath or simply select an existing roughing operation.

- 1 Select **Quick, Finish** from the Toolpaths menu.




The Lathe Quick Finish Properties dialog box opens.

### ► Enter the toolpath parameters


Entering the toolpath parameters for any finish toolpath uses the same workflow as other lathe toolpaths: first you select the tool and tool options, and then you enter the cutting values.

**34** **MASTERCAM X9/** *Facing, Roughing, and Finishing the Outer Diameter*

- 1** Select the finishing tool: **T2121 R0.8**  
**OD FINISH RIGHT - 35 DEG.**




- 2** Decrease the feed rate to **0.2**.




- 3** Keep all other parameters on this page at their default values.

- 4 Click the **Quick finish parameters** tab.




- 5 Change the Finish stepover to **0.3** and the Number of finish passes to **2**.



The operation makes two, finer finish passes and avoids excessive cut depths.

- 6 Leave all other parameters on this page at their default values.

The roughing operation that you created is selected in the Contour to Finish section.



**NOTE:** Only rough and quick rough operations will be available for selecting.

- 7** Click **OK**.





Mastercam creates a finish operation on top of the previous roughing operation.

- 8** Save the part.


### *Exercise 4: Backplotting the Toolpaths*

Backplotting shows the path the tools take to cut your part and lets you spot errors in the program before you send it to the machine. In this exercise, you use Backplot to check the work that you have done.


- 1** Click the **Select all operations** button on the Toolpaths Manager toolbar to select the Face, Rough, and Quick Finish toolpaths that you created.
- 2** Click the **Backplot selected operations** button.



Mastercam Simulator opens in a separate window.




3 Select the **Initial Stock** option in the ribbon bar's Visibility group to see the stock before machining.




- 4 Select the **Initial Stock** option again to view the part profile against a translucent display of the initial stock.



**TIP:** Click to cycle through to view the visibility options in three states: on, translucent, and off.



- 5 For a better view of the operations, use the **Page Up** key to zoom into the part and **[Ctrl + Right Arrow]** to pan the view to the right.




- 6 Click the **Play** button at the bottom of the Simulator screen.



Simulator backplots all three toolpaths with information about the current toolpath motion displayed in the Move List on the right-side of the screen.



- 7 To pause the simulator at the end of each operation, select **Operation change** from the Stop Conditions drop-down.



- 8 Use the Run [R], Step Forward [S], and Backstep [B] keys to view the operations again at your own pace.




---

**TIP:** There are several shortcut keys in Mastercam Simulator that can make your workflow more efficient. See Help for a complete list.

---

- 9 Minimize the Mastercam Simulator, or move it to another monitor.
- You can dock the Mastercam Simulator on a second monitor, and refresh your toolpaths as you make changes.
  - When you close the Mastercam Simulator window, the current layout is saved and used at the application's startup.


The face, rough, and quick finish operations reveal the basic shape of the outer diameter of the hose nozzle. In the next lesson, you further refine the outer diameter with grooves and threads. You also use the additional capabilities of a standard finish operation to efficiently remove material, and check your work against Mastercam Simulator's Verify option.



## LESSON 3

# Adding Grooves and Threads

Grooves and threads are common features on a lathe part. A groove is an indented or recessed area in a workpiece. They can be very difficult to machine with a roughing toolpath or a roughing tool. A thread is the helical ridge of a screw. Both groove and thread toolpaths require that you define the shape and orientation of the operation as well as their cutting values. In this lesson, you create groove and thread toolpaths on the outer diameter of the part. You also see how you can employ plunge parameters to efficiently remove material in a finish operation. To analyze the viability of these operations, you use advanced verification features in the Mastercam Simulator.



### Lesson Goals


- Create groove operations on a single chain and on non-adjacent geometry.
- Use plunge cuts in a finish operation to efficiently remove material.
- Manually enter thread parameters to create a thread on the outer diameter.
- Use Verify and its functions to check your work.

### Exercise 1: Grooving on the Outer Diameter: Multiple Chains


Groove toolpaths are useful for machining indented or recessed areas that are not otherwise machinable by roughing toolpaths or tools. You can machine several grooves in a single operation, even if their geometry never connects. In this exercise, you create one groove operation from two distinct chains.

- 1** Choose **Groove** from the Toolpaths menu.

The Grooving Options dialog box opens.



- 2** Select the **Multiple chains** option.




- 3** Click **OK**.


The Chaining dialog box displays and you are prompted to select an entry point.



- 4 Chain two of the three grooves by selecting the first and last entities of each chain as shown in the illustration.



**TIP:** Right-click in the graphics window, and use **Zoom Window** to more easily select the groove geometry.




- 5 Click **OK** in the Chaining dialog box to accept the chain.




The Lathe Groove (Chain) Properties dialog box opens.

- 6 From the Toolpath parameters tab, select the grooving tool: **T4141 R0.1 W1.85 OD GROOVE CENTER - NARROW**



- 7 Keep all other parameters on this page at their default values.
- 8 Click the **Groove shape parameters** tab, and make sure that all values are as shown.





10 Click the **Groove finish parameters** tab, and make sure that all values are as shown.

Toolpath parameters

Groove shape parameters

Groove rough parameters

Groove finish parameters

☒ Finish

Multiple Passes

☒ Complete all passes on each groove

☐ Complete each pass on all grooves

Number of finish passes:

1

Finish stepover:

2.0

Stock to leave in X:

0.0

Stock to leave in Z:

0.0

☐ Tool back offset number:

41

Direction for 1st pass

☐ CCW

☒ CW

Retraction Moves

☒ Rapid

☐ Feed rate: 0.01

☐ mm/rev

☐ mm/min

Corner Dwell

☒ None

☐ Seconds

☐ Revolutions

0.0

Overlap

☒ Middle overlap

☐ Select overlap

Select Overlap...

Distance from 1st corner: 0.0

Overlap between passes: 0.0

Tool Compensation

Compensation type: Computer

☒ Optimize cutter comp in control

Roll cutter around corners: All

Wall Backoff

% of tool width

5.0

☐ Ignore undercuts

☒ Lead In...


☐ Filter...

☒

☒

☒

11 Click **OK** to create the toolpath.






## Exercise 2: Grooving on the Outer Diameter: Rough Pass Only

In this exercise, you restrict a second groove toolpath to machine just a rough pass on a single, recessed area.


- 1 Choose **Groove** from the Toolpaths menu.
- 2 Select the **Chain** option from the Grooving Options dialog box.



- 3 Click **OK**.


The Chaining dialog box displays and you are prompted to select an entry point.

- 4 Chain the third groove by selecting the first and last entity of the chain as shown in the illustration, and click **OK**.




The Lathe Groove (Chain) Properties dialog box opens.

- 5 Keep **T4141 R0.1 W1.85 OD GROOVE CENTER - NARROW** selected.




- 6 Open the **Groove finish parameters** page, and clear the **Finish** option.

In the next exercise, you use a standard finish operation to remove remaining stock from this groove.



- 7 Click **OK** to create the toolpath.




*Exercise 3: Finishing with Plunge Cuts*


In this exercise, you finish the groove you created. To more efficiently remove the material, you activate plunging in both directions.

- 1 Select **Finish** from the Toolpaths menu.

The Chaining dialog box displays, and you are prompted to select a point or chain contour.




- 2 Select the **Last** button to reselect the geometry chained for the previous grooving operation.




- 3 Click **OK** in the Chaining dialog box to accept the chain.




The Lathe Finish Properties dialog box opens with the finish tool used in the quick finish toolpath (Operation 3) already selected.



- 4 Type **OD - Finish with Plunge** in the Comment field.




## 5 Open the **Finish parameters** page.




You do not need to edit any fields on this page.

## 6 Click the **Lead In/Out** button.




The Lead In/Out dialog box opens.

- a Enter **-135** in the Angle field, or drag the angle dial to define the entry vector.



The tool will follow this angle as it enters the cut.



**b** Click **OK** to return to the Lathe Finish Properties dialog box.

**7** Click the **Plunge Parameters** button.

Plunge Parameters...


The Plunge Cut Parameters dialog box opens. Use this dialog box to define how you want the tool to handle plunges along the toolpath. You can choose to plunge in either or both axes.

- a** Select the option to allow plunging in both directions.
  - The tool plunges into all sections on the chained path.
  - Choosing to plunge in both directions activates the Front and Back clearance angle fields.
- b** Keep the default values for both clearance angle fields.


Clearance angles control how the tool plunges and give additional clearance at the undercut wall.

- The front clearance angle prevents the tool front from cutting with the entire length of the insert's front as the tool cuts up to the wall.

- The back clearance angle prevents the tool back from cutting with the entire length of the insert's back as the tool plunges to the next cut depth.



- c Click **OK** to return to the Lathe Finish Properties dialog box.




**8** Click **OK** to create the toolpath.



**9** Save the part.

**10** (Optional) Backplot the groove and finish toolpaths that you have created in this lesson.



### *Exercise 4: Adding a Thread Toolpath*

A threading toolpath is typically the last toolpath performed on a lathe part because of the need for accuracy. A threaded part has to fit precisely into another part. You can program threads on the OD or ID to secure parts to each other.


With Mastercam, you can directly enter toolpath parameters or select geometry to create a thread toolpath.

In this exercise, you use part geometry to create an OD thread toolpath.




- 1 Choose **Thread** from the Toolpaths menu.

The Lathe Thread Properties dialog box opens.




## ► Select the tool

- 1 From the Toolpath parameters tab, select the thread tool: **T9191 R0.072 OD THREAD LEFT - SMALL**



- 2 Enter **400** into the Spindle speed field, and select the **mm/rev** option for the Feed rate.

The feed and speed rates you enter here overwrite the default settings for this operation.




- 3 Keep all other parameters on this page at their default values.


► **Enter thread shape parameters**

The values you enter into this tab determine the shape of the thread as dictated by its geometry, whether it is cut on the inner diameter, outer diameter, or face/back of the part, and how much variation is allowed.


- 1 Click the **Thread shape parameters** tab.




- 2 In the Lead field, enter **1.5** mm.  
The blueprint on page 41 shows the lead value.




- 3 Click the **Major Diameter** button.  
You are prompted to select a point in the graphics window.




- 4 Click the thread's largest diameter.



- 5 Click the **Minor Diameter** button.  
You are prompted to select a point in the graphics window.



- 6 Click the thread's smallest diameter.




- 7 Make sure that your major and minor values are as shown, and press **[Enter]**.

Mastercam automatically calculates the **Thread depth** from the major and minor diameter values.

Major Diameter...	16.5
Minor Diameter...	13.5
Thread depth:	1.5
Start Position	

- 8 Click the **Start Position** button and select the beginning of the thread from graphics window.
- 9 Click the **End Position** button and select the end of the thread from graphics window.



The fields on the tab show the location of the start and end of the thread on the Z axis.




- 10 Confirm that the Thread orientation is **OD**.

Thread orientation determines whether the thread is created on the inner or outer diameter of the part.

- 11 Click the **Draw Thread** button to preview the thread geometry in the graphics window.

Mastercam creates an outline of the thread.




- 12 Choose **Yes** to save it with your part.

► Enter thread cut parameters


The values entered in this tab define how Mastercam will cut the material.

- 1 Click the **Thread cut parameters** tab.




- 2 Select the **Compute** option on the right side of the dialog box.

Mastercam automatically calculates the required acceleration clearance from the lead and main spindle speed.



3 Keep all other parameters on this page at their default values.



4 Click **OK** to create the toolpath.

5 Save the file.




## Exercise 5: Verifying the Toolpaths


Verifying your toolpaths allows you to use solid models to simulate part machining against a selected stock definition. The result Verify creates represents the surface finish, and shows collisions, if any exist. You can identify and correct program errors before they reach the shop floor.

In this exercise, you use some of Verify's features to check the thread operation you created in this lesson.


- 1 Make sure that the Thread operation is selected in the Toolpaths Manager.




- 2 Click the **Verify selected operations** button.



Verify displays in the Mastercam Simulator window.




- 3 Right-click in the graphics window and change the view to **Isometric**. Pan and zoom into the area that will be threaded.




- 4 Click the **Play** button or press [R] to verify the toolpath.  
Mastercam Simulator verifies the toolpath.


- 5 Open the **Verify** ribbon bar.




- 6 Click **Accurate Zoom**.



Accurate Zoom smooths surfaces when you view the part in close-up.




*Accurate Zoom Off*



*Accurate Zoom On*




**TIP:** Click **Reset Zoom** to restore the original magnification result.




- 7 Click the **True Thread** button, and click **OK** to continue.

True Thread requires that you re-verify the operation.




- 8 Click the **Play** button or press [R] to restart verification.

True Thread displays a more realistic threading motion and helical screw threads, instead of concentric circles and grooves.



*True Thread Off*



*True Thread On*

Toggle the **True Thread** button to return to a quicker, but less accurate verification.

- 9 Minimize the Mastercam Simulator, or move it to another monitor.


You have completed machining the outer diameter. In the next lesson, you will create operations on the C-Axis.



## LESSON 4

# C-Axis Drilling Operations

Lathe C-Axis toolpaths are included with Mastercam for most common contour and drill applications. When you select one of these toolpaths, Mastercam automatically sets the Tplane and Cplane to the appropriate settings for the desired application. These toolpaths also support Y-axis rotation and axis substitution. To use C-axis toolpaths, the active machine definition must support the appropriate axes. In this lesson, you use two operations to drill a hole through the part on the C-axis.



### Lesson Goals


- Create 2D geometry from circular holes in the solid body.
- Add a toolpath group.
- Create a C-Axis drill operation.
- Copy and modify an existing operation to create a new one.

### Exercise 1: Making Drill Geometry


The drill toolpath requires the selection of two-dimensional geometry. Because the method you used to create 2D geometry on page 15 did not create a cross section of the part, the geometry for the drill hole was not created. In this exercise, you use Mastercam's Hole-Axis function to create the necessary geometry from circular holes in the solid body.

- 1 Open the **Level Manager**, and make **Level 1** visible.

The solid model displays in the graphics window.




- 2 Create a Level 3. Name this level, **C-Axis Geometry**.



- 3 Turn on translucent shading in the graphics window to view the interior of the solid.




- 4 Use the Isometric Gview and Zoom to more easily see the model's drill hole.




- 5 Create the C-Axis geometry.

**a** Select **Model Prep, Hole-Axis**.




**b** [Ctrl + click] the internal face of the upper hole to select both openings of the through hole.




**TIP:** Use [Ctrl + click] to select faces with matching diameters.

- c Place points and circles at both the top and bottom of the holes.
- d Click **OK** to accept your changes.



Mastercam creates geometry for both ends of the through hole.




## Exercise 2: Adding a New Toolpath Group


Toolpath groups are subgroups that are “children” of machine groups. They inherit machining properties and other important properties from their parent groups. Toolpath groups house toolpath operations as well as other subgroups. They are useful for creating sets of toolpaths on the same machine that you will want to post separately. Mastercam supports unlimited subgroups.

In this exercise you organize your operations into two different toolpath groups: Outer Diameter and C-Axis Drill.

- 1 Right-click **Toolpath Group-1**, and select **Groups, Rename** from the pop-up menu.
- 2 Change the name of Toolpath Group-1 to **Outer Diameter**.




- 3 Create the C-Axis Drill toolpath group.
  - a Right-click the machine group and select **Groups, New Toolpath group** from the menu.




A new toolpath group is created.



**NOTE:** If necessary, move the insert arrow past the new toolpath group.



- b Rename the new toolpath group:  
**C-Axis Drill.**





*Exercise 3: Creating a C-Axis Drill Operation*


In this exercise, you create a center drill operation with a C-axis drill toolpath.

- 1 Select **Toolpaths, C-axis, C-Axis Drill.**

The Drill Point Selection dialog box opens



- 2 Select the top point or arc using the **Manual** or **Entities** buttons.




**NOTE:** The illustration shows the top arc selected. When you select open or closed arcs, the drill points are placed in the center of the arcs.

When finished, confirm your selection.

- Manual selection: press **[ESC]**.
- Entity selection: press **[Enter]**.

Mastercam confirms that you have one point defined and that point sorting and the duplicate point filter are off.



- 3 Click **OK**.

The C-Axis Toolpath - C-Axis Drill dialog box opens




► Enter the Toolpath Parameters

In addition to selecting tools and entering cutting values, the C-axis drill operation requires that you define the rotary axis motion.


Select the tool

- 1 From the Tree View, open the **Tool** page.




- 2 Click the **Select library tool** button.

The Tool Selection dialog box opens.



- 3 Choose **5.CENTER DRILL** from the list, and click **OK** to return to the Tool page.




**TIP:** Use the Tool List Filter to narrow the tools displayed in the list.






#### 4 In the Comment window, type **C-axis Drill - Center Drill**.




### Define Hole Depth

#### 1 Open the **Linking Parameters** page.



2 Enter an incremental cutting depth of **-3.0**.



3 Keep all other options on the Linking Parameters page at their default values.


Configure Rotary Axis Motion

C-axis toolpaths automatically set the rotation type to **Axis substitution** around the Z axis. This gives you the choice of chaining either flat geometry which will be rolled around the cylinder, or geometry which is already properly positioned in 3D space.

1 Open the **Rotary Axis Control** page.




The **Axis substitution** option is the only rotation type available for C-axis drill operations.




- 2 Set Rotation direction to **CW** (clockwise), and confirm that the **Unroll** option is selected.

Mastercam unrolls the geometry on to a flat plane in a clockwise direction relative to the selected axis. When you post the toolpath, the geometry wraps back onto the cylinder using the axis substitution and rotary diameter parameters.




- 3 Enter the **Rotary diameter**. Use the dimension from the blueprint on page 63, or follow the procedure below.


- a Right-click in the **Rotary diameter** field, and select **D = Diameter of an arc**.



- b** Select the circular edge of the stock.



A built-in calculator reads the dimensions of the selected arc directly into the Rotary diameter field.




- 4** Click **OK** to create the toolpath.
- 5** Save the part.
- 6** Backplot and/or Verify this toolpath following the procedures you learned in Lessons 2 and 3.

### ***Exercise 4: Copying the Drilling Operation***


The final drill operation uses the same geometry and many of the same parameters as the center drill operation you created in Exercise 3. In this exercise, you copy and paste one operation in the Toolpaths Manager in order to quickly create a new one.

- 1 Right-click and drag the drill toolpath you just created to the bottom of the operation list.
- 2 Release the mouse button and choose **Copy after** from the right-click menu.

Mastercam creates a new operation.




- 3 If necessary, move the insert arrow past the new toolpath.




### Exercise 5: Modifying the Drilling Parameters

In this exercise, you create the drill through operation by modifying the parameters in the center drill operation that you copied.

- 1 Click new toolpath's **Parameters** folder to open the dialog box.




**2** Open the **Tool** page.




**3** Click the **Select library tool** button, and select the 6 mm drill.


**4** Type **C-axis Drill** in the Comment field.



**5** Open the **Linking Parameters** page.




- 6 Using the dimension on page 63, enter the cut depth.



- 7 Open the **Tip Comp** page.


Use this page to configure how the tool drills all the way through the stock.



- a Select the **Tip Comp** checkbox to activate the parameters on the page.


- b Enter a **1.0** mm breakthrough amount.

This insures that the full diameter of the tool breaks through the bottom of the stock.



- 8 Click **OK**.

- 9 The new toolpath is marked dirty in the Toolpaths Manager.







## LESSON 5

# Cutoff and Stock Flip

Lathe's miscellaneous operations manipulate the stock and reposition chucks, tail-stocks, and steady rests. Operations can output a comment and a program stop in the NC code to let the operator manually reposition the stock or a peripheral, or they can output code to automatically control peripherals. Mastercam Lathe currently supports the following miscellaneous operations:

- Stock flip (reposition stock on the same spindle)
- Stock transfer (reposition stock to a different spindle)
- Stock advance (program a bar feeder)
- Chuck (clamp/unclamp/reposition)
- Tailstock (advance/retract)
- Steady rest reposition

In this lesson, you prepare for machining the inner diameter with Mastercam's cutoff and stock flip operations.

### *Lesson Goals*


- Create a cutoff operation.
- Program a stock flip.

### *Exercise 1: Cutting Off the Part*


Cutoff toolpaths vertically cut off pieces of the part, such as sections of bar stock. You do not need to chain any geometry for a cutoff toolpath. Instead, you select the point where the part is cut off.

In this exercise, you use the options in the cutoff toolpath to separate the part from the bar stock.

**1** Select **Toolpaths, Cutoff**.



**2** Select the cutoff boundary point at the point indicated.




**TIP:** To view the part as illustrated:

- change the GView to **Top**
- hide Level 1
- turn off the toolpath display [**Alt + T**]

The Lathe Cutoff Properties dialog box opens.

- 3 Select the cutoff tool: **T151151 R0.4 W4. OD CUTOFF RIGHT.**




- 4 Click the **Stock Update** button to open the Stock Update Parameters dialog box.

Use this dialog to define whether the stock model will be based on the finished part or leftover stock after the cutoff operation.


- a Select the **Keep separated piece** option.

Mastercam will display the part boundary after the part is cut from the stock.

- b Click **OK**.



5 Open the **Cutoff parameters** tab.



6 Select the **From stock** option.

Mastercam computes the **Entry amount** from the maximum stock diameter at the Z coordinate of the cutoff boundary point.


7 Select **Chamfer** to cut a chamfer on the corner of the part.

8 Click **Parameters** to enter chamfer dimensions in the Cutoff Chamfer dialog box.

- a** Enter **0.25** in the Width field

The chamfer is defined by its width. Mastercam automatically calculates the height from this dimension and the angle.

- b** Click **OK** to return to the Cutoff parameters tab.



- 9** Click **OK** to create the operation.
- Mastercam cuts the part from the stock.
- 10** Save the part.

## Exercise 2: Programming a Stock Flip

A stock flip lets you program operations on the opposite side or back of a lathe part in the same Mastercam file. Stock flip operations output a comment and program stop in the NC code, which lets the operator manually remove the stock and reposition (flip) it in the chuck.


In this exercise, you program the new stock and chuck position.



**IMPORTANT:** You can only program miscellaneous operations such as a stock flip when they are supported by the active machine definition.


- 1 Use the procedure on page 68 to create a new toolpath group. Rename the group **Back/Inner Diameter**.

The new toolpath group will include the stock flip and the operations machining the back and inner diameter of the part.




- 2 Select **Toolpaths, Misc Ops, Stock Flip**.

The Lathe Stock Flip Properties dialog box opens.



► **Re-align Part Geometry**


Use the options in the Lathe Stock Flip Properties dialog box to make a copy of part geometry that is aligned with the new stock model and to remove the original geometry from view.

 **NOTE:** Mastercam blanks the original entities. They are not deleted. (See Help for more information on blanked entities.)

- 1 If necessary, select the **Transfer geometry** and **Blank original geometry** options.
- 2 Click the **Select** button under the Transfer geometry option.


Mastercam returns you to the graphics window.

- 3 Window-select the entire part, and press **[Enter]**.



All entities are selected.

- 4 In the Level Options section, offset the level of the transfer geometry by **100**.






## ► Enter new stock and chuck jaw positions

Use this procedure to define the new stock position and the final position of the chuck jaws after the stock flip.


- 1 To position the transferred stock, click the **Select** button, and choose any point on the back edge of the part.

Stock Position

Original Position:	Transferred Position:
 Z: <input type="text" value="0.0"/>	 Z: <input type="text" value="0.0"/>
<input type="button" value="Select..."/>	<input type="button" value="Select..."/>



As indicated by the image in the dialog box, the point you select (Z -89.0) will be transferred to Z0 after the stock flip operation







**TIP:** The point you choose does not have to be on the face of the stock. You can choose any convenient reference point.

- 2 To set the final position of the chuck jaws, click the **Select** button, and chose the point as indicated from the graphics window.


This is where the chuck jaws will grip the stock after the stock flip operation.

Chuck Position

☐ Diameter only

Original Position:	Final Position:
 D: <input type="text" value="38.2"/>	 D: <input type="text" value="38.2"/>
 Z: <input type="text" value="-94.0"/>	 Z: <input type="text" value="-94.0"/>
<input type="button" value="Select..."/>	<input type="button" value="Select..."/>





**3** Click **OK** to create the operation.

The stock and chuck display in the graphics window in their transferred positions.



**4** Save the part.


The part is now in the correct position for you to machine the features of the back end and inner diameter.



## LESSON 6

# Machining the Inner Diameter

In this lesson you create the toolpaths necessary to machine the inner diameter (ID) of the hose nozzle. You may notice that many of the toolpaths need only to be slightly adjusted to be applied to work on the inner diameter. After you have completed creating the toolpaths, you use Verify's display tools to inspect your work.



### Lesson Goals

- Create new tools based on existing tools
- Create toolpath operations on the inner diameter of the part
- Use Verify's display tools to inspect your work

### Exercise 1: Creating New Tools in the Lathe Tool Manager

The interior of the hose nozzle part is hollow. You use two drill operations to cut the longest two inner diameters. Both operations require creating new tools that match the diameter of each drill hole (9.6 mm and 11.4 mm). The third and widest inner diameter requires roughing and finishing tools that fit within dimensions of the bore (24.5 mm), as well as an ID threading tool that can cut to the thread standard for garden hoses (GHT).


Although your shop may choose to use standard tools to cut these toolpaths, in this exercise you create all of these tools in the Lathe Tool Manager.

► **Create the 9.6 mm drill**


The 9.6 mm drill is based upon a 9 mm drill that is already in the tool library.

**1 Select Toolpaths, Lathe Tool Manager.**

The Tool Manager opens. The upper window displays the tools used in the current Mastercam file.



**2 Click and drag T123123 9. Dia DRILL 9. DIA from the library window to the part window.**



When you create or work on a tool in the part window, you are working on a the tool definition that is stored in the machine group. That means if you edit


a tool from the part window, you are only changing the definition in the machine group and not the tool library. If you import the tool from another Mastercam file, the changes you make here will not appear in the original file.



**TIP:** Select the **Filter Active** option to filter the list of tools. Click the **Filter** button to change the filter criteria with the Lathe Tool Filter dialog box.


- 3 Using the right-click menu, copy and paste the 9 mm drill in the part window.
- 4 When prompted, click **Yes** to add a similar tool.

A copy of the 9 mm drill is added to the part window.




- 5 Right-click the copied tool, and select **Edit tool** from the menu.

The Define Tool dialog box opens.




6 Edit the tool geometry as shown.


These values define the dimensions of the new tool insert.



7 Click the **Holders** tab, and edit the dimensions of the holder.




8 Click the **Parameters** tab and rename the tool.



9 Click **OK** to finalize your changes.



The new tool profile displays in the part window.




## ► Create the 11.4 mm drill

Repeat Steps 3 – 9 to create the 11.4 mm drill.

- Enter the following values to create the tool and holder dimensions.
- Rename the tool: **DRILL 11.4 DIA.**



The original tool and the two new tools display in the part window.



## ► Create the ID roughing tool

- 1 Click and drag **T7171 R0.4 ID ROUGH MIN 16. DIA - 80 DEG.** from the library window to the part window.
- 2 Right-click the tool, and select **Edit tool** from the menu.

The Define Tool dialog box opens.



### 3 Choose **05** from the IC Dia./Length drop-down.

Select Catalog... LATHE\_MM.LIC ☐ Filter insert shape in catalog

Get Insert... Save Insert Delete Insert... ☒ Metric Values

Insert Name: CCMT 09 T3 04 Tool Code:

Insert Material Cerbid

Shape

T (triangle) R (round)

C (80 deg. diamond) D (55 deg. diamond)

IC Dia. / Length 05 Insert Width 05 Thickness T3 Corner Radius 04

Relief Angle C (7 deg.)

Cross Section

N Q

R T


This value defines the insert's IC diameter or length (depending on the selected shape). The IC diameter (IC = inscribed circle) is determined by placing a circle in the insert shape and measuring the circle's diameter

### 4 Leave the other parameters on this tab at their default values, and click the **Boring Bars** tab.


Type - Boring bar Inserts Boring Bars Parameters

Select Catalog... LATHE\_MM.LIC ☐ Filter inser

- 5 Change the holder geometry as shown to fit the newly edited insert.



- 6 Click the Parameters tab, and rename the tool: **ID ROUGH MIN. 10. DIA. - 80 DEG.**




- 7 Click **OK** to finalize your changes.

## ► Create the ID finishing tool

Create a finishing tool for the bore you will turn.


- 1 In the part window, use the right-click menu to copy and paste the tool you just edited (ID ROUGH MIN. 10. DIA. - 80 DEG).
- 2 When prompted, click **Yes** to add a similar tool.
- 3 Right-click the copied tool, and select **Edit tool** from the menu.  
The Define Tool dialog box opens.

- 4 Enter the following values to create the insert's inscribed circle diameter and a smaller corner radius.



**TIP:** You can either enter dimensions directly or select them from the drop-down menu.

- 5 Keep the holder geometry as shown to fit the newly edited insert.




- 6 Name the new tool: **ID FINISH MIN. 10. DIA. - 80 DEG.**
- 7 Click **OK** to finalize your changes.

## ► Create the ID threading tool


- 1 Click and drag **T101101 R0.036 ID THREAD MIN. 20. DIA.** from the library window to the part window.
  - 2 Right-click the tool, and select **Edit tool** from the menu.
- The Define Tool dialog box opens.

- 3** Edit the insert geometry by increasing the lead (mm/thread) and cutting depth (C) of the insert.

Mastercam uses these values to calculate the default feed rate based on the spindle speed value entered on the Parameters page.



- 4** On the Holders tab, decrease the diameter of the holder (A) to **12.0**.



- 5** Click the Parameters tab, and rename the tool: **ID THREAD MIN. 12. DIA.**
- 6** Click **OK** to finalize your changes.

You have now finished creating the tools that you need to machine the inner diameter of the part.

- 7** Click **OK** to exit the Lathe Tool Manager.

## ***Exercise 2: Facing the Back of the Part***

It is a best practice to prepare the back face of the part for further machining. Create a Face toolpath using the default roughing tool (T0101 R0.8 OD ROUGH RIGHT - 80 DEG) to finish the back face of the part to Z0.

Use the same procedure to face the back of the part as you used to face the front. If you feel you still need instruction to create this operation, refer back to Lesson 2, Exercise 1 (page 23).


### Exercise 3: Drilling the First Inner Diameter

Drill operations in Lathe are on the center line of the part and are placed by default at the part origin.

#### 1 Select **Toolpaths, Drill**.


The Lathe Drill Properties dialog box opens.

Unlike most toolpaths, lathe drill toolpaths do not require you to select geometry before entering the toolpath parameters.




#### 2 Select the 9.6 mm drill from the tool window.



If desired, enter comments for the toolpath.




#### 3 Click the **Simple drill - no peck** tab.




- 4 Click the **Depth** button to define the bottom of the drill hole from a point in the graphics window.
- 5 Select the point indicated.




Mastercam returns you to the Lathe Drill Properties dialog box and automatically enters the correct value in the Depth field.



- 6 Choose **Peck Drill** from the Cycle drop-down list.



The parameters tab changes from **Simple drill - no peck** to **Peck drill - full retract**.



The name that appears on this tab depends on the cycle you select in the Drill Cycle Parameters drop-down list. The cycles which are available to you depend on the active control definition.

- 7 Set the depth for the first and all subsequent peck moves to 2.0 mm.

Drill Cycle Parameters

Cycle:  
Peck Drill

1st peck 2.0

Subsequent peck 2.0

Peck clearance 0.0


Retract amount 0.0

Dwell 0.0

Shift 0.0

- 8 Click **OK** to complete the operation.

The graphics window displays how the first inner diameter is drilled.




### Exercise 4: Drilling the Second Inner Diameter

This operation uses the depth calculator to adjust the drilling depth of the tool.

- 1 Select **Toolpaths, Drill**.

- 2 Select the 11.4 mm drill from the tool window.


If desired, enter comments for the toolpath.



- 3 Click the **Peck drill - full retract** tab.


Mastercam remembers the last drill cycle you selected.

- 4 Click the **Depth** button to define the bottom of the new toolpath's drill hole.
- 5 Select the point indicated.






The depth of the drill hole at the selected point is automatically entered in the Depth field.




Although you did not select the tip of the drill hole, you can use Mastercam's depth calculator to calculate the proper drilling depth based on the finish diameter and drill size.

- 6 Click the **Depth Calculator** button.




The Depth Calculator dialog box opens.

With the **Use current tool values** option selected, Mastercam displays the tool diameter, tool tip included angle, and tool tip diameter for the tool you choose on the Toolpath parameter page. It calculates the proper drilling depth and adds it to the existing depth.




- 7 Click **OK** to return to the Lathe Drill Properties dialog box.

The depth of the bottom of the drill point is entered into the field.



- 8 Leave all other parameters in the dialog box as is, and click **OK** to create the operation.




### *Exercise 5: Roughing and Finishing the Third Inner Diameter*

In this exercise, you bore the third inner diameter with roughing and finishing operations. With the exception of a standard finish toolpath, the roughing and finishing operations that you create on the inner diameters are very similar to the toolpaths you created on the outer diameter (Lesson 2).

- 1 Select the **Rough** toolpath from the Toolpaths menu.

The Chaining dialog box displays and you are prompted to select an entry point.

- 2 Click the geometry to create a partial chain as shown.




- 3 Click **OK** in the Chaining dialog box to accept the chain.




The Lathe Rough Properties dialog box opens.


- 4 Select the ID roughing tool you created on page 94: **ID ROUGH MIN 10. DIA - 80 DEG.**



- 5 Type **ID - Rough** in the Comment field.




## 6 Change the following cutting values on the **Rough parameters** tab.




- Change the Depth of cut to **1.0**.
- Decrease the Stock to leave in Z to **0.05**.
- Select **Use stock for outer boundary** from the Stock Recognition drop-down.

## 7 Click the **Lead In/Out** button.


The Lead In/Out dialog box opens.




a Click the **Lead out** tab.




b Enter **0.5** in the Length field.



This is the length of the vector the tool follows as it retracts from the part.



- c Click **OK** to return to the Lathe Rough Properties dialog box.
- 8 Keep all other parameters in the dialog box at their default values.
- 9 Click **OK** to create the rough toolpath.



- 10 Use **ID FINISH MIN. 10. DIA. - 80 DEG** to finish the bore you just roughed with a new operation. (This is the finishing tool you created on page 96.) Leave all settings at their default values.
- 11 Save the part.


Exercise 6: Adding an ID Thread

- 1 Choose **Thread** from the Toolpaths menu.  
The Lathe Thread Properties dialog box opens.




**NOTE:** You do not need to select geometry to create a thread toolpath.


- 2 From the Toolpath parameters tab, select the thread tool you created on page 97: **ID THREAD MIN 12 DIA.**



- 3 Enter **400** into the Spindle speed field, and select the **mm/rev** option for the Feed rate.





- 4 Type **ID - Thread** in the Comment field.



- 5 Keep all other parameters on this page at their default values.

- 6 Click the **Thread shape parameters** tab.



- 7 Refer to the illustration above to enter the following thread dimensions:

- lead
- major and minor diameters
- start and end positions


The blueprint on page 89 also shows these values.



**TIP:** If you are cutting a standard thread, click **Select from table** to display a list of standard thread tables. Mastercam will automatically fill in the fields for the thread dimensions with values from these tables. See Mastercam Help for more information.




- 8 Confirm that the thread orientation is **ID**.
- 9 Click the **Thread cut parameters** tab.



- 10 If necessary, select the **Compute** option to calculate the required acceleration clearance.
- 11 Keep all other parameters on this page at their default values.

**12** Click **OK** to create the toolpath.




**13** Save the part.

### ***Exercise 7: Refining Your Verification Results***


In Lesson 3, you used Accurate Zoom and True Thread to more clearly see your work. In this exercise, you use Verify's Part Sectioning tools to view the cuts you made along the inner diameter.

- 1 Select operations 12 through 17 in the Toolpaths Manager.

These are all the operations you created on the inner diameter.




- 2 Click the **Verify selected operations** button.




Verify displays in the Mastercam Simulator window.

- 3 Hide the fixture, and change the stock opacity to translucent.



- 4 Turn the **Color Loop** on to view each operation's change to the stock as a different color.




The color of each operation is also represented as a different color on the playback bar.




**TIP:** Improve your view by panning, zooming, and rotating.

- 5 Click the **Play** button or press **[R]** to verify the toolpath.




Although you are able to view the operations through the translucent stock, Mastercam Simulator's clipping plane and part sectioning tools offer an even better view of the part's interior.

- 6 Change the stock back to opaque.




- 7 Open the **Verify** ribbon bar.




- 8 Select the **XY Clipping Plane** button.

A cross-section is drawn through the stock's XY plane.




**TIP:** Click and drag the plane to position the cross-section.




- 9 Click the **XY Clipping Plane** button again to turn it off.


- 10 Select a quadrant from the 3/4 sectioning menu.



Part sectioning displays your stock in 3/4 sections using a combination of two clipping planes. Once you select a section, you can click and drag either plane to adjust the view.



- 11 Click **3/4, Off** to turn off part sectioning.



You have finished cutting the part. In the next lesson, you organize your tools and post your work to the machine.





# LESSON 7

## Post Output

Posting refers to the process by which the toolpaths in your Mastercam part files are converted by a specialized processing program to a format that can be understood by your machine tool's control.

Tool numbers that are output to your NC file come from the Toolpath Parameters tab or Tool page for each operation. When you select a tool for an operation, Mastercam generates a default tool number and default tool offsets. If your machine only accepts a limited range of tool numbers, Mastercam lets you reassign tool numbers for operations in a machine group.

In the final lesson of this tutorial, you renumber the tools used in the operations you created, and then post the entire set to the NC file.


### *Lesson Goals*

- Renumber all tools used to cut the part
- Post your work for inspection

### *Exercise 1: Renumbering Tools*


In this exercise, you renumber the tools for each operation.

- 1 Select all operations in the Toolpaths Manager.




- 2 Right-click the machine group.

**3** Select **Edit selected operations, Renumber tools** from the menu.



The Renumber tools dialog box displays.

**4** Clear the last option to renumber tools that are not used in any operation.



**5** Click **OK**.

The tools in the Toolpaths Manager are renumbered relative to the current order of the operations.



**TIP:** Use the procedure above to reassign tool numbers after you have already created toolpaths. To number tools in the machine group by operation before you create toolpaths, select the option on the Tool Settings tab in the Machine Group Properties dialog box.

## Exercise 2: Posting


In this exercise, you post the operations in the machine group.

- 1 If necessary, select all operations in the Toolpaths Manager.
- 2 Click the **Post selected operations** button in the Toolpaths Manager toolbar.



**NOTE:** If you have not selected all the operations in a machine group, Mastercam will ask if you want to post all the operations.

The Post processing dialog box displays. Mastercam uses these settings to handle the files that are generated when posting.



Click **OK**.

The Save As dialog box displays.


- 3 Rename the file, or click **Save** to accept the default NC file name.

Mastercam posts the file, and it is opened in your default file editor. Use the generated text file to evaluate your post before sending it to the machine.

# Conclusion

Congratulations! You have completed the *Getting Started with Mastercam Lathe* tutorial. Now that you have mastered the skills in this tutorial, explore Mastercam's other features and functions.

You may be interested in other tutorials that we offer. The Mastercam tutorial series is in continual development, and we will add modules as we complete them. Visit our website, or select **Tutorials** from the **Help** menu to see the latest publications.



## Mastercam Resources

Enhance your Mastercam experience by using the following resources:

- *Mastercam Help*—Access Mastercam Help by selecting **Help, Contents** from Mastercam's menu bar or by pressing [**Alt+H**] on your keyboard. Also, most dialog boxes, function panels, and ribbon bars feature a Help button that opens Mastercam Help directly to related information.
- *Mastercam Reseller*—Your local Mastercam Reseller can help with most questions about Mastercam.
- *Technical Support*—CNC Software's Technical Support department (860-875-5006 or [support@mastercam.com](mailto:support@mastercam.com)) is open Monday through Friday from 8:00 a.m. to 5:30 p.m. USA Eastern Standard Time.
- *Mastercam Tutorials*—CNC offer a series of tutorials to help registered users become familiar with basic Mastercam features and functions. The Mastercam

tutorial series is in continual development, with new modules added as we complete them. Visit our website, or select **Tutorials** from the **Help** menu to see the latest publications.

- *Mastercam University*—CNC Software sponsors Mastercam University, an affordable online learning platform that gives you 24/7 access to Mastercam training materials. Take advantage of more than 180 videos to master your skills at your own pace and help prepare yourself for Mastercam Certification. For more information on Mastercam University, please contact your Authorized Mastercam Reseller, visit [www.mastercamu.com](http://www.mastercamu.com), or email [training@mastercam.com](mailto:training@mastercam.com).
- *Online communities*— You can find a wealth of information, including many videos, at [www.mastercam.com](http://www.mastercam.com).

For tech tips and the latest Mastercam news, follow us on Facebook ([www.facebook.com/mastercam](http://www.facebook.com/mastercam)), Twitter ([www.twitter.com/mastercam](http://www.twitter.com/mastercam)), or Google+ ([plus.google.com/+mastercam](http://plus.google.com/+mastercam)). Visit our YouTube channel to see Mastercam in action ([www.youtube.com/user/MastercamCadCam](http://www.youtube.com/user/MastercamCadCam))!

Registered users can search for information or ask questions on the Mastercam Web forum, [forum.mastercam.com](http://forum.mastercam.com), or use the knowledge base at [kb.mastercam.com](http://kb.mastercam.com). To register, select **Help, Link on Mastercam.com** from the Mastercam menu and follow the instructions.

## Mastercam Documentation

Mastercam installs the following documents in the \Documentation folder of your Mastercam installation:

- *What's New in Mastercam X9*
- *Mastercam X9 Installation Guide*
- *Mastercam X9 Administrator Guide*
- *Mastercam X9 Transition Guide*
- *Mastercam X9 Quick Reference Card*
- *Mastercam X9 ReadMe*



## Contact Us

For questions about this or other Mastercam documentation, contact the Technical Documentation department by email at [techdocs@mastercam.com](mailto:techdocs@mastercam.com).



**Attention! Updates may be available.  
Go to [Mastercam.com/Support](http://Mastercam.com/Support) for the latest downloads.**

***cnyc software, inc.***

671 Old Post Road  
Tolland, CT 06084 USA  
[www.mastercam.com](http://www.mastercam.com)